USEPA 290 BROADWAY NY, NY

NOTIFICATION OF DEMOLITION AND RENOVATION PAL JOB # 16-1055

| Operator Project # | Postmark | Da | ate Received | | | Notification # | | | |
|---|-----------------|---------------------|--------------|--|--------|---------------------------------------|-----------------------------|---------------|--|
| TYPE OF NOTIFICATION (O-C | Driginal, R-Rec | reived, C-Cancelled | n: 0 - 0 | Original | | | | | |
| TYPE OF NOTIFICATION (O-Original, R-Received, C-Cancelled): O – Original FACILITY INFORMATION (Identify Owner, Removal Contractor and Other Operator): | | | | | | | | | |
| OWNER NAME: RXR 530 Fifth Office Owner LLC | | | | | | | | | |
| Address: 530 Fifth Avenue 3 rd Floor | | | | | | | | | |
| City: New York State: NY Zip: 10036 | | | | | | | | 10036 | |
| Contact Name: Nicholas Mather Telephone: 212-840-2057 | | | | | | | | | |
| REMOVAL CONTRACTOR: PAL Environmental Safety Corp. d/b/a PAL Environmental Services | | | | | | | | | |
| Address: 11-02 Queens Plaza | | | | | | | | | |
| City: Long Island City | | | | State: NY | | | Zip: 11101 | | |
| Contact Name: Aric Domozick Telephone: 718-349-0900 | | | | | | | | 900 | |
| OTHER CONTRACTOR: | | | | | | | | | |
| Address: | | | | | | | | | |
| | City: | | | | | | | Zip: | |
| Contact Name: | 0011 | | | Telephone: | | | | | |
| TYPE OF OPERATION (D-Demo, O-Ordered Demo, R-Renovation, E-Emergency Renovation: R | | | | | | | | | |
| IS ASBESTOS PRESENT? (YES NO) YES | | | | | | | | | |
| FACILITY DESCRIPTION (Include Building Name, Number and Floor or Room Number) | | | | | | | | | |
| Building Name: | | | | | | | | | |
| Address: 530 5 th Avenue | | | | | | | | | |
| City: New York | | | | State: NY | | | Zip: 10036 | | |
| Site Location: 27 th Floor Roo | of | | | | | | | | |
| Building Size: 446,678 Square Feet | | | | # of Floors: 26 | | | Age in Years: 59 | | |
| Present Use: Commercial | | | | Prior Use: Commercial | | | | | |
| Procedure, Including Analytical Method, If Appropriate, Used to Detect the Presence of Asbestos Material: PLM — Polarized Light Microscopy | | | | | | | | | |
| | PLI | 4 – Polarized Light | MICROSC | ору | | | | | |
| Approximate amount of asbes | tos | R. ACM | | Non-Friable Indicate Unit of Measurer | | | t of Management | | |
| Including | , | to be | | Asbestos Material not to be removed | | Indicate Unit of Measurement Below | | | |
| 1. Regulated ACM to be rem | oved | removed | | | | | | | |
| 2. Category I ACM not remo | ved | | | not to be removed | | | | | |
| Category II ACM not remo | oved | | | | | | | 74.775 | |
| | | | | CAT I | CAT II | | | UNIT | |
| | | | | | | | | | |
| | | | | | | | | | |
| Surface Area: | | | | | | Linear Feet: Ln | | Ln M: | |
| Surface Area: Tar, Flashing & Material | & Roofing | 1,448 | | | | Square Fe | et: X | Square Meter: | |
| Volume RACM off Facility Com | ponent | | | | | CuFt: | | Cu M: | |
| Scheduled Dates Asbestos Removal (mm/dd./yy) | | | Sta | art: 06/0 6 | 5/2016 | Complete: | Complete: 06/01/2017 | | |
| Scheduled Dates Demo/Renovation (mm/dd./yy) | | | Sta | Start: | | Complete: | | | |
| | | | | | | | | | |

| DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION AND RENOVATION STTE: HEPA Vacs, Micro Traps (Negative Air Pressure) and amended water will be utilized for emissions control. WASTE TRANSPORTER #1 Name: Tri State Transfer Associates Address: 1199 Randall Avenue City: Long Island City Contact Name: Jimmy Byrne WASTE TRANSPORTER #2 Name: ATC Address: 2 Moriches Middle Island Road City: Shirley Contact Name: Kenny Smith Telephone: 631-924-5050 WASTE TRANSPORTER #3 Name: PALE, Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Male, Environmental Safety Corp. d/b/a PAL Environmental Services Location: 9000 Minerva Road, SE FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-STITLED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) Signature of Orne (Poperator Description of Procedure in Subpart of Procedure i | # R | | | | | | | |
|--|--|-----------------------------------|----------------------------------|--|--|--|--|--|
| DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION AND RENOVATION STTE: HEPA Vacs, Micro Traps (Negative Air Pressure) and amended water will be utilized for emissions control. WASTE TRANSPORTER #1 Name: Tri State Transfer Associates Address: 1199 Randall Avenue City: Long Island City Contact Name: Jimmy Byrne WASTE TRANSPORTER #2 Name: ATC Address: 2 Moriches Middle Island Road City: Shirley Contact Name: Kenny Smith Telephone: 631-924-5050 WASTE TRANSPORTER #3 Name: PALE, Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Male, Environmental Safety Corp. d/b/a PAL Environmental Services Location: 9000 Minerva Road, SE FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-STITLED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) Signature of Orne (Poperator Description of Procedure in Subpart of Procedure i | DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD (S) TO BE USED: | | | | | | | |
| THE DEMOLITION AND RENOVATION SITE: HEPA Vacs, Micro Traps (Negative Air Pressure) and amended water will be utilized for emissions control. WASTE TRANSPORTER #1 Name: Tri State Transfer Associates Address: 1199 Randall Avenue City: Long Island City Contact Name: Jimmy Byrne Telephone: 718-617-0771 WASTE TRANSPORTER #2 Name: ATC Address: 2 Moriches Middle Island Road City: Shirley State: NY Zip: Contact Name: Kenny Smith Telephone: 631-924-5050 WASTE TRANSPORTER #3 Name: Kenny Smith Telephone: 631-924-5050 WASTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE Location: 9000 Minerva Road, SE Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: Explanation of how the event caused unsafe conditions or the | DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT | | | | | | | |
| WASTE TRANSPORTER #1 Name: Tin State Transfer Associates Address: 1199 Randall Avenue City: Long Island City State: NY Zip: 10474 Contact Name: Jimmy Byrne Telephone: 718-617-0771 WASTE TRANSPORTER #2 Name: ATC Address: 2 Moriches Middle Island Road City: Shirley State: NY Zip: Contact Name: Kenny Smith Telephone: 631-924-5050 WASTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT Aly INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFT PART 61, SUBPART M), WILL BE ON- STIED DURING THAT AND INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFT PART 61, SUBPART M), WILL BE ON- STIED DURING THAT PROVISION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) 04/14/2016 Date | THE DEMOLITION AND RENOVATION SITE: | | | | | | | |
| Name: P.A. Evironmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City Contact Name: Jimmy Byrne WASTE TRANSPORTER #2 Name: ATC Address: 2 Moriches Middle Island Road City: Shirley Contact Name: Kenny Smith Telephone: 631-924-5050 WASTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City City: Long Island City City: Long Island City Telephone: 718-349-900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-fraible ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFT PART 61, SUBPART M), WILL BE ON- STEE DURING THE PEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O4/114/2016 Signature of Ornary Operator Date | HEPA Vacs, Micro Traps (Negative Air Pressure) and amended water will be utilized for emissions control. | | | | | | | |
| Address: 1199 Randall Avenue City: Long Island City Telephone: 718-617-0771 WASTE TRANSPORTER #2 Name: ATC Address: 2 Moriches Middle Island Road City: Shirley State: NY Zip: Contact Name: Kenny Smith Telephone: 631-924-5050 WASTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- STEE DURING THAT DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) 94/14/2016 Date | WASTE TRANSPORTER #1 | | | | | | | |
| City: Long Island City | Name: Tri State Transfer Associates | | | | | | | |
| Contact Name: Jimmy Byrne WASTE TRANSPORTER #2 Name: ATC Address: 2 Moriches Middle Island Road City: Shirley State: NY Zip: Contact Name: Kenny Smith Telephone: 631-924-5050 WASTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE City: Waynesburg FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O4/14/2016 Signature of Owner Operator Date | Address: 1199 Randall Avenue | | | | | | | |
| Contact Name: Jimmy Byrne WaSTE TRANSPORTER #2 Name: ATC Address: 2 Moriches Middle Island Road City: Shirley State: NY Zip: Contact Name: Kenny Smith Telephone: 631-924-5050 WASTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./wy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O4/14/2016 Signature of Owner Operator Date | City: Long Island City | State: NY | Zip: 10474 | | | | | |
| WASTE TRANSPORTER #2 Name: ATC Address: 2 Moriches Middle Island Road City: Shirley State: NY Zip: Contact Name: Kenny Smith Telephone: 631-924-5050 WASTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OF PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) 94/14/2016 Signature of Owner Operator Date | 2.01.10171 | | | | | | | |
| Address: 2 Moriches Middle Island Road City: Shirley State: NY Zip: Telephone: 631-924-5050 WASTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O4/14/2016 Signature of Owner Operator Date | | | | | | | | |
| City: Shirley Contact Name: Kenny Smith WASTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O4/14/2016 Signature of Owner Operator Date | | | | | | | | |
| Contact Name: Kenny Smith Telephone: 631-924-5050 WASTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O4/14/2016 Signature of Ontal Operator Date | | | | | | | | |
| Contact Name: Kenny Smith WASTE TRANSPORTER #3 Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mill poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O4/14/2016 Signature of Origin Operator Date | City: Shirley | State: NY | 7in: | | | | | |
| Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./ryy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O4/14/2016 Signature of Owner/Operator Date | Contact Name: Kenny Smith | | | | | | | |
| Name: P.A.L. Environmental Safety Corp. d/b/a PAL Environmental Services Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE Lity: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- STITE DURING THE PEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) Signature of Owner/Operator I certify that the above information is correct | | | | | | | | |
| Location: 11-02 Queens Plaza South City: Long Island City City: Long Island City Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-STITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) Signature of Owner, Operator I certify that the labove information is correct | | onmental Services | | | | | | |
| City: Long Island City Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) Signature of Owner/Operator I certify that the above information is correct | Location: 11-02 Queens Plaza South | | | | | | | |
| Telephone: 718-349-0900 Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O4/14/2016 Signature of Owner/Operator I certify that the apove information is correct | | City: Long Island City | City: Long Island City | | | | | |
| Disposal Facility Name: Minerva Enterprises Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O4/14/2016 Signature of Owner/Operator I certify that the above information is correct | | oley Long Island City | City. Long Island City | | | | | |
| Name: Minerva Enterprises Location: 9000 Minerva Road, SE City: Waynesburg State: OH Zip: 44688 FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) 04/14/2016 Signature of Owner/Operator Date I certify that the above information is correct | | | | | | | | |
| City: Waynesburg FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE PEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O4/14/2016 Signature of Owner/Operator Date I certify that the above information is correct | | | | | | | | |
| City: Waynesburg FOR EMERGENCY RENOVATIONS Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE PEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O4/14/2016 Signature of Owner/Operator Date I certify that the above information is correct | | Location: 9000 Minerya Road | ÇF | | | | | |
| Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O4/14/2016 Signature of Owner/Operator Date I certify that the above information is correct | A December 1 March 1 and | | | | | | | |
| Date and Hour of Emergency (mm/dd./yy) Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) 04/14/2016 Signature of Owner/Operator Date I certify that the layove information is correct | | | | | | | | |
| Description of the Sudden, Unexpected Event: Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) 04/14/2016 Signature of Owner/Operator Date I certify that the above information is correct | | | | | | | | |
| Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden: DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O4/14/2016 Signature of Owns Operator Date I certify that the above information is correct | Description of the Sudden, Unexpected Event | | | | | | | |
| NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O4/14/2016 Signature of Owner/Operator Date I certify that the above information is correct | Explanation of how the event caused unsafe conditions or | would cause equipment damage or a | n unreasonable financial bunden. | | | | | |
| NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED OR REDUCED TO POWDER. Any ACM, which is discovered unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) Od/14/2016 Signature of Owner/Operator Date I certify that the above information is correct | DESCRIPTION OF PROCEDURE TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ACREE TO BE FOUND OF PROCEDURE TO BE FOUND IN THE EVENT THAT UNEXPECTED ACREE TO BE FOUND OF PROCEDURE. | | | | | | | |
| Unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and cleaned up with HEPA Vacs, to be put in 6 mil poly bags for proper disposal. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O4/14/2016 Signature of Owner/Operator Date I certify that the above information is correct | NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVEDIZED OR REDUCED TO DOMOGRA ASSASSIANT ASSASSIA | | | | | | | |
| I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) O4/14/2016 Signature of Owner/Operator Date I certify that the above information is correct | unexpectedly, or non-friable ACM, which becomes crumbled, will be immediately wet with amended water and closed or with the a | | | | | | | |
| I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGUALTION (40 CFT PART 61, SUBPART M), WILL BE ON- SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) Od/14/2016 Signature of Owner/Operator Date I certify that the above information is correct | Vacs, to be put in 6 mil poly bags for proper disposal | | | | | | | |
| THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulgation) Odd/14/2016 Signature of Owner/Operator I certify that the above information is correct | I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULAL TION (40 CET DART 61, SURDART AN) MALL RE ON | | | | | | | |
| Signature of Owner/Operator I certify that the above information is correct Date O4/14/2016 Date | SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY | | | | | | | |
| Signature of Owner/Operator Date I certify that the above information is correct | THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS (required 1 year after promulation) | | | | | | | |
| Signature of Owner/Operator Date I certify that the above information is correct | half | | | | | | | |
| Signature of Owner/Operator Date I certify that the above information is correct | 04/14/2016 | | | | | | | |
| I certify that the acove information is correct | Circulture of O Oll Wo | | | | | | | |
| A V/A \ | I certify that the apove information is correct | | | | | | | |
| 04/14/2016 | N VN I | 04/14/2016 | Superior and the | | | | | |
| Signature of Owner/Operator Date | | | | | | | | |
| Date | , , , , , , , , , , , , , , , , , , , | Date | | | | | | |

· ----